

City of Detroit
Department of Recreation Performance Audit
Exhibit 1 – Maheras Center



Cobwebs in the corner.



Dimly lit hallway.

City of Detroit
Department of Recreation Performance Audit
Exhibit 1 – Maheras Center



Exposed electrical outlet.



Exposed pipe due to deteriorating insulation.